


Attachments
previously
int

17 7 0252

17551




de maximis, inc.

9041 Executive Park Drive
Suite 401
Knoxville, TN 37923
(615) 691-5052

January 25, 1993

Mr. Fred B. Stroud - OSC
USEPA - Region IV
345 Courtland Street, NE
Atlanta, GA 30365


**Reference: Saad Trousdale Drive Site
Transmittal of Analytical Data**

Dear Mr. Stroud:

As you requested and pursuant to Section VI Paragraph 8 of the Administrative Order by Consent (AOC) Docket No. 92-34-C, all analytical data received since our last transmittal of December 22, 1992 are provided with this letter. Data transmitted in this package include samples collected and analyzed from the former Oil/Water Separator (OWS) area, the Body Shop trench, and the trench along the southern perimeter of the Saad property adjacent to the Franklin Brick building. These samples were collected between 12/15/92 and 1/15/93. Attached with the data are the chain-of-custody/request for analyses forms, which were submitted to Specialized Assays with the samples. Also enclosed is the CLP data package for sample BST-010 which includes matrix spike and matrix spike duplicate results from the analytical laboratory.

Please note that the sample results attached have not been subjected to full data validation procedures at this point. The quality control/quality assurance QA/QC validation process is not scheduled until the completion of site characterization/removal activities (see schedule in the RA/FI Phase II Work Plan). As such, these data should be considered as preliminary until DRE Remedial Services completes their QA/QC validation process in conformance with the project schedule and with the QA/QC requirements established in Section VI Paragraphs 7 and 8 of the AOC.

Respectively,
de maximis, inc.


Bennie L. Underwood
Project Coordinator

RLD/lah

Attachments

cc: Beth Davis - ORC
Saad Site Technical Committee ✓

File\data4\lfr\disk\1: 3034-03